

Incident Report for 7/20/2021 Environmental Incident (Incident ID: 578)

Initial Update Close Out

Incident Details		Reporting Party Details			
Description:	Lighting strike Bullrock LLC	Incident Date and Time:	7/20/2021 10:25 PM		
Incident Type:	Environmental Incident	Incident Subtype :	Fire		
Source Type:	Fixed Facility	Source Subtype:			
Incident Status:	Active	Released Into Medium :	Paved Ground, Soil		
Site Details		Reporting Party Name: Holly Mills			
Is Spill Continuous:	No	Reporting Party Company:	Bullrock LLC		
Discovered/Start Date and Time:	7/20/2021 10:25 PM	Reporting Party Phone:			
Is Spill Contained:	Yes	Reporting Party Email:			
End Date and Time:	7/21/2021 04:00 AM	Reported Date and Time:	7/21/2021 11:30 AM		
Reported to NRC:	Yes	Incident Location			
Well Name :	ALFRED BROWN SWD	Address: 11033 30th St NW, Watford City, ND 58847			
Oil/Gas Operator :	BULLROCK LLC	Location Description:			
Company Name:	Bullrock LLC	Latitude:	47.8601050112028		
Facility Address:	11033 30th St NW, Keene, ND 58847	Longitude:	-102.944170456019		
Extent of Spill/Release:	Extent Undetermined	Section:	34		
Extent Details:		Range:	96 W		
		Quarter:	NE¼		
		Qquarter:	NE¼		
		Source Water Protection Area:			
		County/Tribe:	McKenzie County		
		Fire District:	KEENE FIRE		
Incident Contacts					
Responsible Authority Contact		Responsible Authority Compliance Contact		Property Owner Contact (Property Owner is Informed)	
Name:	Timothy Redpath	Name:	Holly Mills	Name:	
Title:	Managing Member	Title:	Managing Member	Company Name:	
Company Name:	Bullrock LLC	Company Name:	Bullrock LLC	Company Address:	
Company Address:	PO Box 456, Watford City, ND 58854	Company Address:	P.O. Box 456, Waterford City, ND 58854	Phone:	
Phone: 701-641-1619	24 Hr.Phone:	Phone: 701-641-1619	24 Hr.Phone:	Email:	
Email:	Mobile/Pager:	Email:	Mobile/Pager:		

Incident Report for 7/20/2021 Environmental Incident (ID: 578)

Incident and Risks

Expected Cause of Fixed Facility Fire : Weather
 Weather : Light Rain
 Distance from Nearest Occupied Building :
 Distance from Nearest Water Well :
 Known Health Risks : None Known

Nature of Locale where Incident Occurred : Other: Salt Water Disposal
 Wind Direction :
 Wind Speed :
 Number of Confirmed Injuries : 0
 Number of Confirmed Fatalities : 0

Immediate Potential Threats (first 24 Hr) :

None of the Above: No known immediate threats

Delayed Potential Threats (after first 24 hr) :

None of the Above: No known potential threats

Response Details

Estimated Clean Up Completion Date :
 Protective Actions Taken : Fire Department Called
 Evacuations :
 Shelter In Place :
 Clean Up Action Taken : Vac trucks on location

Waste Disposal Location : IHD
 Other Response Details :
 No Response Reason :

Incident Chemicals/Released Substances

Pesticides/Herbicides are not involved

CAS Number	Name	Trade Name	Is EHS	Is Radioactive	Estimated Volume	Estimated Volume in Barrels	Estimated Volume in Pounds	Recovered Volume	Recovered Volume in Barrels
N/A	produced water	Produced Water	No	No	820 bbl	820	0	0 bbl	0

Incident Observations

Note Added Date	Incident Observations
9/15/2021	Visited site on 090821. Took photos. No work had begun as of this date. Company representative indicated cleanup would begin at the end of the week or early next week.
8/4/2021	On location 8/4/21, at 1:02pm. No changes since previous inspections. I spoke with RP and was told they are waiting on insurance company before continuing work. Further follow up is required.
8/4/2021	Inspection Date: 7/28/2021 Arrived on location at 1450. Spoke with a Bullrock employee. No further work had been done on the spill area. Further follow up is needed to ensure proper clean up. Photos were taken and can be found in the report folder.
8/4/2021	Inspection Date: 7/26/2021. Arrived on location at 1858. There is a skid steer on location with some dirt work done. The saltwater spill is starting to discolor the crop further in the field. Further follow up is needed. Photos were taken and can be found in the report folder.
7/22/2021	Arrived on location at 1030 on 7/22/2021. Spoke with landowner and RP personnel. Earthsystems is coming to delineate area and make berms, Londowner gave samples he would like to get tested for group 190. Spill flow is to the north of pad to an unknown distance. There is a stream to the north about a quarter mile that needs to be monitored. Walked down to test water but it is dry. Photos were taken and can be found in report folder.
7/22/2021	Added photos to folder sent by the landowner/tenant.
7/22/2021	Spoke with Bullrock representatives about remediation plan. At this time Bullrock is looking for dirt work contactors to start the soil removal. A environmental third party is coming out today to look over the site. Further follow up is needed.
7/21/2021	Release due to lightning strike, caused produced water to be release on and off location. Follow up is required.