

Incident Report for 3/20/2021 Oil/Gas Spill (Incident ID: 245)

Initial Update Close Out

Incident Details		Reporting Party Details		
<p>Description: The crude oil spill occurred due to a failed valve on piping going into tank TK-1904 at the Divide Station, which is approximately 45 miles north of Williston, ND. The Divide Station is located at the intersection of 96th St NW and Highway 85. The GPS coordinates are 48.807289, -103.617021. The spill was contained inside the secondary containment berm surrounding TK-1904 and did not migrate off site.</p> <p>Incident Date and Time: 3/20/2021 10:30 AM</p>		<p>Reporting Party Name: Tarik Ibrahim</p> <p>Reporting Party Company: Summit Midstream Partners, LP</p> <p>Reporting Party Phone:</p> <p>Reporting Party Email:</p> <p>Reported Date and Time: 3/20/2021 9:21 PM</p>		
<p>Incident Type: Oil/Gas Spill</p> <p>Source Type: Fixed Facility</p> <p>Incident Status: Active</p>		<p>Incident Subtype: Valve/Piping Connection Leak</p> <p>Source Subtype:</p> <p>Released Into Medium: Soil</p>		
Site Details		Incident Location		
<p>Is Spill Continuous: No</p> <p>Discovered/Start Date and Time: 3/20/2021 10:30 AM</p> <p>Reported to NRC: Yes</p> <p>Well Name:</p> <p>Oil/Gas Operator:</p> <p>Company Name: Polar Midstream, LLC</p> <p>Facility Address: 13298 96th St., NW, Fortuna, ND 58844</p> <p>Extent of Spill/Release: Confined to Property of Origin - Secondary Containment</p> <p>Extent Details: The amount of crude oil spilled is estimated to be 532 bbls at this time. The spill did not migrate outside of the secondary containment and there are no potential impacts to surface or ground water.</p>		<p>Address: 13298 96th St., NW, Fortuna, ND 58844</p> <p>Location Description:</p> <p>Latitude: 48.8072889999992 Longitude: -103.617020999998</p> <p>Section: 1 Township: 161 N</p> <p>Range: 100 W Quarter: NW¼</p> <p>Qquarter: NW¼ Source Water Protection Area:</p> <p>County/Tribe: Divide County Fire District: FORTUNA FIRE</p>		
<p>Is Spill Contained: Yes</p> <p>End Date and Time: 3/20/2021 01:14 PM</p> <p>NDIC File Number:</p> <p>Oil/Gas Field Name:</p> <p>Facility Name: Divide Station (Tier II Facility ID: 21223)</p> <p>Nature of Business: Oil and Gas</p>				
Incident Contacts				
Responsible Authority Contact		Responsible Authority Compliance Contact		Property Owner Contact
<p>Name: Tarik Ibrahim</p> <p>Title: Manager, Environmental & Permitting</p>		<p>Name: James Johnston</p> <p>Title: EVP, General Counsel & Chief Compliance Officer</p>		

Incident Report for 3/20/2021 Oil/Gas Spill (ID: 245)

Company Name: Summit Midstream Partners, LP
Company Address: 910 Louisiana Street, Suite 4200, Houston, TX 77002

Phone: 720-358-3846 24 Hr.Phone:

Email: Mobile/Pager:

Name: Tarik Ibrahim
Title: Manager, Environmental & Permitting

Company Name: Summit Midstream Partners, LP
Company Address: 910 Louisiana Street, Suite 4200, Houston 77002

Phone: 720-358-3846 24 Hr.Phone:

Email: Mobile/Pager:

Company Name: Summit Midstream Partners, LP
Company Address: 910 Louisiana Street, Suite 4200, Houston, TX 77002

Phone: 832-930-6503 24 Hr.Phone:

Email: Mobile/Pager:

Name: James Johnston
Title: EVP, General Counsel & Chief Compliance Officer

Company Name: Summit Midstream Partners, LP
Company Address: 910 Louisiana Street, Suite 4200, Houston 77002

Phone: 832-930-6503 24 Hr.Phone:

Email: Mobile/Pager:

Incident Report for 3/20/2021 Oil/Gas Spill (ID: 245)

Incident and Risks

Expected Cause of Fixed Facility Valve/Piping Connection Leak : Unknown
 Nature of Locale where Incident Occurred : Oil and Gas Facilities

Weather : Windy
 Wind Direction : Southeast
 Wind Speed : 10-15 mph

Distance from Nearest Occupied Building : 1.3 miles
 Number of Confirmed Injuries : 0

Distance from Nearest Water Well : 1.6 miles
 Number of Confirmed Fatalities : 0

Known Health Risks : The spill only impacted material inside the secondary containment and did not have the potential to migrate off site. The spill did not have the potential to impact surface or ground water.

Immediate Potential Threats (first 24 Hr) :

None of the Above: The spill only impacted material inside the secondary containment and did not have the potential to migrate off site. The spill did not have the potential to impact surface or ground water.

Delayed Potential Threats (after first 24 hr) :

None of the Above: The spill only impacted material inside the secondary containment and did not have the potential to migrate off site. The spill did not have the potential to impact surface or ground water.

Response Details

Estimated Clean Up Completion Date :
 Waste Disposal Location :
 Protective Actions Taken : Upon discovery, Summit operations personnel promptly activated emergency response contractors to stop the source of the spill and recover spilled crude oil.
 Other Response Details :
 Evacuations :
 No Response Reason :
 Shelter In Place :
 Clean Up Action Taken : The source of the leak was stopped and free standing liquid continues to be removed with a hydrovac.

Incident Chemicals/Released Substances

Pesticides/Herbicides are not involved

CAS Number	Name	Trade Name	Is EHS	Is Radioactive	Estimated Volume	Estimated Volume in Barrels	Estimated Volume in Pounds	Recovered Volume	Recovered Volume in Barrels
N/A	Crude Oil		No	No	532 bbl	532	163045.96	400 bbl	400

Incident Observations

Note Added Date	Incident Observations
12/2/2022	Arrived at location at 1255 on 11/22/2022. The grass inside and outside of the location looked to have done well last summer. Further follow up is needed with Summit on the progress of monitoring. Photos were taken and can be found in the attachments.
3/26/2021	3/25/2021.NDDEQ put out a press release.Press release in the attachments.More follow up is necessary.
3/26/2021	Arrived on location 3/25/2021.Release contained within containment of tank battery capable of holding a massive release. Responsible company has hired a contractor to cleanup the release and is excavating the impacted soil. Contractor is going to provide more data.
3/22/2021	According to the incident report, the release was contained to the well pad. NDIC retains oversight.